







Sharp edges, burrs and loose shavings shall be removed.
 Unspecified surfaces = Ra 3.6



Information online: <http://www.f2d.dk/equipment/model/cg-meter.htm>
 Plastic part for CG cardan: <http://shpws.me/Mg2v>

Rev:	Revision text:	Change order nr:	Date:	Sign:	
Material:	Tolerance:	Colour:			
Status:	Surface treatment:				
 F2D.dk www.f2d.dk 		Sheet:	Scale:	Date:	Sign:
Description:		Item number:			
CG-Meter for F2D		CG-meter			
		A4	1:5	23/7 16	HF