





Sharp edges, burrs and loose shavings shall be removed.  
 Unspecified surfaces = Ra 3.6



Rev:	Revision text:	Change order nr:	Date:	Sign:
Material:	Tolerance:	Colour:		
Status:	Surface treatment:			
 <b>F2D.dk</b> <a href="http://www.f2d.dk">www.f2d.dk</a> 	Sheet:	Scale:	Date:	Sign:
	A4	1:2	23/7-16	HF
Description:	Item number:			
Pointer for CG-Meter	CG-meter			